




— P R O —

Герметичный кабельный ввод в трубу
для греющего кабеля





(RUS)

Инструкция по эксплуатации

1. Втулка с внешней резьбой (23 мм гаечный ключ)
2. Уплотнительные шайбы
3. Силиконовая прокладка
4. Вставка к трубе с внешней резьбой 2" (23 мм гаечный ключ)
5. Посадка к трубе с внешней резьбой 3/4" или 1" (27 или 36 мм гаечный ключ)
6. Наконечник теплового кабеля, не входит в комплект

Установить составляющие части сборки TMpro в порядке, указанном на рисунке. Посадку 5 выбирают в зависимости от размера узла T.

(DEU)

Bedienungsanleitung

Kabelverschraubung (23 mm Mausschlüssel)

Dichtungsring auf beiden Seiten der Gummidichtung

Dichtung

Verschraubung mit R 1/2" Aussengewinde (23 mm Mausschlüssel)

Zwischenstutzen mit R 3/4" oder R 1" Außengewinde (27 oder 36 mm Mausschlüssel)

Endabschluss des Heizkabels, der nicht mit im Paket ist.

Die Teile der Druckdurchführung TMpro gemäß der Abbildung auf das Heizkabel aufschieben.

Das Zwischenstutzen (5) ist vom Diameter des T-Stückes abhängig.

(ENG)

Operation instruction

1. Barrel nut (23 mm set wrench)
2. Support plates on both sides of the rubber gasket
3. Gasket
4. Seal seat with R 1/2" external thread (23 mm set wrench)
5. Fit with R 3/4" or R 1" external thread (27 or 36 mm set wrench)
6. The end shutting of the heating cable, which is not included in the package

Thread the parts of the pressure lead-through TMpro in the order shown in the figure above.

The size of the fit (5) depends on the size of the T-connection.